1.1 Request For Change form

RFC Nr: ASA08/03

To be used whenever requesting a change to any part of FOM. This form may be photocopied as required.

1. SUBJECT: Amend the CONTACT/MONITOR table in FOM 8.3.1

2. REASON FOR CHANGE:

The MONITOR/CONTACT information in the table below is not strictly correct (at least as far as YBBB and YMMM are concerned). We would expect inbound aircraft to be instructed to Contact/Monitor Brisbane/Melbourne rather than YBBB/YMMM.

3. DESCRIPTION OF PROPOSAL: [attach additional pages if necessary]

Update the FOM table (8.3.1) as follows. Other ATSUs may seek a similar amendment to their frequency transfers

<u>FIR</u>	CPDLC Instruction		
Anchorage	CONTACT PAZA CENTER [frequency]		
Oceanic			
Antananarivo			
(Madagascar)			
Auckland	MONITOR NZZO CENTER [frequency]		
Oceanic			
Brisbane	MONITOR YBBB BRISBANE CENTER [frequency]		
Columbo			
Honiara ¹	MONITOR YBBB BRISBANE CENTER [frequency]		
Johannesburg			
Maldives			
Mauritius			
Melbourne	MONITOR YMMM MELBOURNE CENTER [frequency]		
Nadi	MONITOR NFFF CENTER [frequency]		
Nauru ¹	MONITOR YBBB BRISBANE CENTER [frequency]		
Oakland	CONTACT KSFO CENTER [frequency]		
	KSFO (San Francisco Radio) will provide all primary and secondary HF		
	frequencies, and HF transfer points along the route of flight.		
Tahiti	CONTACT NTTT CENTER [frequency]		
	A SELCAL check is required.		
Fukuoka	CONTACT FUKUOKA CENTER [frequency]		

4. REFERENCE(S):			
5. PERSON INITIATING:	Adam Watkin	DATE:	4 th Mar 2008
ORGANISATION: Airservices Australia			
TEL/FAX/EMAIL:	adam.watkin@airservicesaustralia.com		
6. CONSULTATION	RESPONSE DUE BY DATE:		
Organisation	Name	Agree/Disagree	Date
7. ACTION REQUIRED:			
8. FOM EDITOR		DATE REC'D:	
9. FEEDBACK PASSED		DATE:	